



<http://www.dot.ca.gov/hq/traffops/signtech/mutcdsupp/pdf/camutcd/CAMUTCD-Part2.pdf>

California Manual on Uniform Traffic Control Devices for Streets and Highways
(FHWA's MUTCD 2003 Edition, as amended for use in California)

Section 2C.35 NO PASSING ZONE Sign (W14-3)

Standard:

The NO PASSING ZONE (W14-3) sign (see Figure 2C-6) shall be a pennant-shaped isosceles triangle with its longer axis horizontal and pointing to the right. When used, the NO PASSING ZONE sign shall be installed on the left side of the roadway at the beginning of no-passing zones identified by either pavement markings or DO NOT PASS signs or both (see Sections 2B.29 and 3B.02).

Option:

The NO PASSING ZONE (W14-3) sign may be used at the beginning of no-passing zones identified by either pavement markings or DO NOT PASS signs or both (see Sections 2B.29 and 3B.02).

http://epg.modot.org/index.php?title=903.6_Warning_Signs

903.6.37 NO PASSING ZONE Sign (W14-3) (MUTCD Section 2C.35)

The NO PASSING ZONE (W14-3) sign is not to be used on a system-wide basis.

It is intended for special use at locations where passing crashes are present and as a measure to correct those accidents.